FAU BOT Approved
August 23, 2022

Educational Plant Survey

Amended

Florida At lantic Univ ersity

Effective

August 2022-June 30, 2025

trtr

Educational Plant Survey

Amended Educational Plant Survey Checklist

EPS Survey Year: Amended 2022

Please contact Ken Ogletree in the Board of Governors ¶office to schedule and set up an initial coordination and procedures discussion necessary for Florida Atlantic University to complete the survey process within the fiscal year. Mr. Ogletree can be reached at (850) 245-9254 or via email at Kenneth.Ogletree@flbog.edu.

c: Mr. Tim Jones, Vice Chancellor, Finance & Administration/Chief Financial Officer
Kenneth Ogletree, Sr. Architect
Kristine Azzato, Facilities Planner
Azita Dotiwala, Director of Budget and Planning, Florida Atlantic University
Corina Mavrodin, Space Coordinator of Utilization and Analysis, Florida Atlantic University

Educational Plant Survey

Building Condition Assessment Form

EPS Survey Year : 2020-2021
University : FAU

This report lists the Building Condition Assessment forms for all the buildings that turned 25 years old since the last Educational Plant Survey.

Document Title	Document Type	Document Comment	Document Sent Date
Arts and Letters Arts & Humanities Arts and Letters	Building Condition Form	Bldg. 52	3/11/2021

BUILDING SYSTEM CONDITION SURVEY
STATE UNIVERSITY SYSTEM OF FLORIDA
2020

FLORIDA ATLANTIC UNIVERSITY Date:

Building No.

1994 26

		Condition Code:	1
Window/Glazing:	Condition Code:	1	
Exterior Wall:	Condition Code:	1	
Foundation:	ConditionCode:	1	
Exterior Doors	Condition Code:	1	
		Condition Code:	1
		Condition Code:	1
HVAC System:	Condition Code:	1	
Elevator Systems:	Condition Code:	1	
		Condition Code:	1
Lighting	Condition Code:	1	
Grounding	Condition Code:	1	
Internal Distribution	Condition Code:	1	
		Condition Code:	1
Fixtures	Condition Code:	1	
Piping	Condition Code:	1	
Building Interior		Condition Code:	1
Doors	Condition Code:	1	
Ceilings	Condition Code:	1	
Floors	Condition Code:	1	
Walls/Partitions	Condition Code:	1	
Life Safety Systems		Condition Code:	1
Fire Alarm	Condition Code:	1	
Fire Suppression	Condition Code:	1	
Emergency Generator	Condition Code:	1	

Notes:

Name, Title

Requ2.2walajd (.608 0 Td (. Needs mocos0405 0.027 T9p7nT CoNpal.j /TT50ximate cogreater thed replaceme an 25% of the estimated)Tj -

1 Satisfactory. Building component is suitable for continued use with normal maintenance.

2 Renewal A Needs minimal capital renewal. The approximate cost is not greater than 25% of the estimated replacement cost of the component.

3 Renewal B Needs mocos0405 0.027 T9p7nT CoNplaal.j /TTroxiTj ital renewal.j /TT50%an 25% -1.the estimatmate cost is not gre

4

5 Replacement Component should be replaced.

BUILDING SYSTEM CONDITION SURVEY
STATE UNIVERSITY SYSTEM OF FLORIDA
2020

University Name: FLORIDA ATLANTIC UNIVERSITY Date: 11.19.2020

Building Name: ARTS & LETTERS - PERFORMING ARTS Building No. 51

Building Occupancy Date: 1994 Building Age: 26

Building Envelope:		Condition Code: 1.5
Window/Glazing:	Condition Code:	1
Exterior Wall:	Condition Code:	2
Foundation:	ConditionCode:	1
Exterior Doors	Condition Code:	2
Building Roof System:		Condition Code: 2
Mechanical Systems:		Condition Code: 1.5
HVAC System:	Condition Code:	2
Elevator Systems:	Condition Code:	1
Electrical System:		Condition Code: 1
Lighting	Condition Code:	1
Grounding	Condition Code:	1
Internal Distribution	Condition Code:	1
Plumbing System:		Condition Code: 1
Fixtures	Condition Code:	1
Piping	Condition Code:	1
Building Interior		Condition Code: 1
Doors	Condition Code:	1
Ceilings	Condition Code:	1
Floors	Condition Code:	1
Walls/Partitions	Condition Code:	1
Life Safety Systems		Condition Code: NA
Fire Alarm	Condition Code:	1
Fire Suppression	Condition Code:	1
Emergency Generator	Condition Code:	1

Notes:

Completed By: Fady Iskarous - DCS Project Mananger
Name, Title

Condition Codes:

1 Satisfactory. Building component is suitable for continued use with normal maintenance.

2 Renewal A Needs minimal capital renewal. The approximate cost is not greater than 25% of the estimated replacement cost of the component.

3 Renewal B Needs more than minimal capital renewal. The approximate cost is greater than 25% but not greater than 50% of the estimated replacement cost of the component.

4 Renewal C Requires major capital renewal. The approximate cost is greater than 50% of the replacement cost of the component.

5 Replacement Component should be replaced.

BUILDING SYSTEM CONDITION SURVEY
STATE UNIVERSITY SYSTEM OF FLORIDA
2020

FLORIDA ATLANTIC UNIVERSITY Date:

Building No.

1994 26

		Condition Code:	1.5
Window/Glazing:	Condition Code:	1	
Exterior Wall:	Condition Code:	1	
Foundation:	ConditionCode:	1	
Exterior Doors	Condition Code:	3	
		Condition Code:	N/A
		Condition Code:	
HVAC System:	Condition Code:		

BUILDING SYSTEM CONDITION SURVEY
STATE UNIVERSITY SYSTEM OF FLORIDA
2020

University Name: FLORIDA ATLANTIC UNIVERSITY Date: 12/4/2020

Building Name: COLLEGE OF EDUCATION Building No. 47

Building Occupancy Date: 1993 Building Age: 27

Building Envelope:		Condition Code: 1.25
Window/Glazing:	Condition Code:	1
Exterior Wall:	Condition Code:	2
Foundation:	ConditionCode:	1
Exterior Doors	Condition Code:	1
Building Roof System:		Condition Code: 2
Mechanical Systems:		Condition Code:
HVAC System:	Condition Code:	
Elevator Systems:	Condition Code:	1
Electrical System:		Condition Code: 2
Lighting	Condition Code:	2
Grounding	Condition Code:	2
Internal Distribution	Condition Code:	2
Plumbing System:		Condition Code: 1.5
Fixtures	Condition Code:	1
Piping	Condition Code:	2
Building Interior		Condition Code: 1.25
Doors	Condition Code:	1
Ceilings	Condition Code:	1
Floors	Condition Code:	2
Walls/Partitions	Condition Code:	1
Life Safety Systems		Condition Code: 1
Fire Alarm	Condition Code:	1
Fire Suppression	Condition Code:	1
Emergency Generator	Condition Code:	1

Notes: 1. Exterior windows need washing 4. Certain areas of floring in the hallways need replacement.
2. Exterior wall need painting
3. Some sections of metal frames supporting stairs are very rusty at the first floor landi due to water intrusion

Completed By: William Mbwambo, Project Manager, DCS
Name, Title

Condition Codes:

1	Satisfactory. Building component is suitable for continued use with normal maintenance.
2	Renewal A. Needs minimal capital renewal. The approximate cost is not greater than 25% of the estimated replacement cost of the component.
3	Renewal B. Needs more than minimal capital renewal. The approximate cost is greater than 25% but not greater than 50% of the estimated replacement cost of the component.
4	Renewal C. Requires major capital renewal. The approximate cost is greater than 50% of the replacement cost of the component.
5	Replacement. Component should be replaced.

BUILDING SYSTEM CONDITION SURVEY
STATE UNIVERSITY SYSTEM OF FLORIDA
2020

University Name: FLORIDA ATLANTIC UNIVERSITY Date: 11/23/2020

Building Name: COLLEGE OF EDUCATION KIOSK Building No. 47-A

Building Occupancy Date: 1993 Building Age: 27

Building Envelope:		Condition Code: 1
Window/Glazing:	Condition Code:	1
Exterior Wall:	Condition Code:	1
Foundation:	ConditionCode:	1
Exterior Doors	Condition Code:	1
Building Roof System:		Condition Code: 1
Mechanical Systems:		Condition Code: 1
HVAC System:	Condition Code:	1
Elevator Systems:	Condition Code:	1
Electrical System:		Condition Code: 1
Lighting	Condition Code:	1
Grounding	Condition Code:	1
Internal Distribution	Condition Code:	1
Plumbing System:		Condition Code: 1.5
Fixtures	Condition Code:	1
Piping	Condition Code:	2
Building Interior		Condition Code: 1
Doors	Condition Code:	1
Ceilings	Condition Code:	1
Floors	Condition Code:	1
Walls/Partitions	Condition Code:	1
Life Safety Systems		Condition Code: N/A
Fire Alarm	Condition Code:	
Fire Suppression	Condition Code:	
Emergency Generator	Condition Code:	

Notes: 1. The structure apears to be in very good condition

Completed By: William Mbwambo, Project Manager, DCS
Name, Title

Condition Codes:

1 Satisfactory. Building component is suitable for continued use with normal maintenance.

2 Renewal A. Needs minimal capital renewal. The approximate cost is not greater than 25% of the estimated replacement cost of the component.

3 Renewal B. Needs more than minimal capital renewal. The approximate cost is greater than 25% but not greater than 50% of the estimated replacement cost of the component.

4 Renewal C. Requires major capital renewal. The approximate cost is greater than 50% of the replacement cost of the component.

5 Replacement. Component should be replaced.

BUILDING SYSTEM CONDITION SURVEY
STATE UNIVERSITY SYSTEM OF FLORIDA
2020

University Name: FLORIDA ATLANTIC UNIVERSITY Date: 11.30.2020

Building Name: LIBERAL ARTS BUILDING Building No. BC49

Building Occupancy Date: 1994 Building Age: 26

Building Envelope:		Condition Code: 1
Window/Glazing:	Condition Code:	1
Exterior Wall:	Condition Code:	1
Foundation:	ConditionCode:	1
Exterior Doors	Condition Code:	1
Building Roof System:		Condition Code: 2
Mechanical Systems:		Condition Code: 2
HVAC System:	Condition Code:	
Elevator Systems:	Condition Code:	2
Electrical System:		Condition Code: 1.75
Lighting	Condition Code:	2
Grounding	Condition Code:	1
Internal Distribution	Condition Code:	2
Plumbing System:		Condition Code: 1
Fixtures	Condition Code:	1
Piping	Condition Code:	1
Building Interior		Condition Code: 1
Doors	Condition Code:	1
Ceilings	Condition Code:	1
Floors	Condition Code:	1
Walls/Partitions	Condition Code:	1
Life Safety Systems		Condition Code: 1
Fire Alarm	Condition Code:	1
Fire Suppression	Condition Code:	1
Emergency Generator	Condition Code:	1

Notes:

Completed By: Fady Iskarous - DCS Project Manager
Name, Title

Condition Codes:

1 Satisfactory. Building component is suitable for continued use with normal maintenance.

2 Renewal A. Needs minimal capital renewal. The approximate cost is not greater than 25% of the estimated replacement cost of the component.

3 Renewal B. Needs more than minimal capital renewal. The approximate cost is greater than 25% but not greater than 50% of the estimated replacement cost of the component.

4 Renewal C. Requires major capital renewal. The approximate cost is greater than 50% of the replacement cost of the component.

5 Replacement. Component should be replaced.

EPS Survey Year: Amended 2022-2023
University: FAU

Buildings with Unsatisfactory Conditions

This is a list of buildings with unsatisfactory building conditions to be included in the Educational Plant Survey for Validation.

Occupy DT	Site ID	Building ID	Building Name	Building condition	Permanent	Act Gross Sq Ft	Comments
196611	1	9	ARTS AND LETTERS	Renovation	Y	110,366	

	Building Condition		Act Gross Sq Ft	Comments
ON	Satisfactory Space		3,2[illegible]	-
ON	Satisfactory Space		4,240	-

15 re f Q q 1 0 0 1 2.444397 [illegible]51 0.71 p rg3465. 0.004 Tc -0.004 Tw 11.04 0 0 11.0

EPS Survey Year: Amended 2022-2023
University: FAU

Occupy Date	Site ID	Building ID	Building Name	Building Condition	Permanent	Act Gross Sq Ft	Comments
199005	1	0043	SCIENCE BUILDING	Renovation	Y	128,250	

EPS Survey Year: Amended 2022-2023
University: FAU

Amended Needs Assessment

This report includes the sum of the room areas rolled up at the university level for the five Educational Plant Survey report.

EPS Survey Year: Amended 2022-2023

University: FAU

SITE ID	SITE NAME	BLDG ID	BLDG NAME	CLASSROO	STUDY	TEACHINC LAB	OFFICE	Research Lab

EPS Survey Year: Amended 2022-2023

University: FAU

Amended Complete Inventory

SITE ID	SITE NAME	BLDG ID	BLDG NAME	CLASSROO	STUDY	TEACHINC LAB	OFFICE	Research Lab	AUDIT/ EXHIB.	INSTRUCT MEDIA	GYM	Campus Support Service
1	FAU BOCA RATON	86	COLLEGE OF BUSINESS	15,249	1,003	6,058	5,854	0	0	0	0	0

EPS Survey Year: Amended 2022-2023

University: FAU

Amended

EPS Survey Year: Amended 2022-2023

University: FAU

Amended Complete Inventory

EPS Survey Year: Amended 2022-2023

University: FAU

Amended Complete Inventory

SITE ID	SITE NAME	BLDG ID	BLDG NAME	

EPS Survey Year: Amended 2022-2023

University: FAU

Amended Complete Inventory

SITE ID	SITE NAME	BLDG ID	BLDG NAME	CLASSROO	STUDY	TEACHINC LAB	OFFICE	Research Lab	AUDIT/ EXHIB.	INSTRUCT MEDIA	GYM	Campus Support Service
1	FAU BOCA RATON	107	SCHMIDT FAMIL COMPLEX FOR ACADEMIC AND ATHLETIC EXCELLENCE	0	287	0	473	0	0	0	0	0
7	FAU DANIA BCH	ST01	SEATECH RESEARCH CENTER	1802	743	1,284	8,225	14,366	1,622	0	0	2,982
18	FAU HARBOR BRAN	HB33	SMALL BOATS MARINA	0	0	1,159	1,293	0	0	0	0	1,507
1	FAU BOCA RATON	31-E	STUDENT ACTIVITIES CENTER	0	200		1,073	0	0	0	0	0
8	FAU											

EPS Survey Year: Amended 2022-2023

University: FAU

Amended Complete Inventory

SITE ID	SITE NAME	BLDG ID	BLDG NAME	CLASSROOM	STUDY	TEACHING LAB	OFFICE	Research Lab	AUDIT/ EXHIB.	INSTRUCT MEDIA	GYM	Campus Support Service
1	FAU BOCA RATON											

EPS Survey Year: Amended 2022-2023
University: FAU

Unsatisfactory Space to be Terminated Terminated

EPS Survey Year: Amended 2022-2023
University: FAU

Unsatisfactory S ‰ be to De molished

This report includes the sum of the room areas rolled up at the building level for the

EPS Survey Year: Amended 2022-2023
University: FAU

Unsatisfactory Space with No Action Required

This report includes the sum of the room areas rolled up at the building level for the five-year Educational Plant Survey. The buildings have been flagged by the University as 'Unsatisfactory Space with No Action Required. –

NO DATA TO REPORT

EPS Survey Year: Amended 2022-2023
University: FAU

Unsatisfactory Space to be Remodeled/Renovated

This report includes the sum of the room areas rolled up at the building level for the five-year Educational Plant Survey. The buildings have been flagged by the university as 'Unsatisfactory Space to be Remodeled/Renovated. –

Site ID	Site Name	Bldg ID	Building Name	Building Condition	Classroom	Study	Teaching Lab	Office	Research Lab	Audit	Instruc / Media	Gym	Campus Support	Be Fund Cat
1	FAU BOCA RATON	9	ARTS AND LETTERS ARTS AND LETTERS	Renovation	6,827	-	13,406	8,835	-	20,334	1,352	-	-	EDUC_ GENERAL
1	FAU BOCA RATON	47	COLLEGE OF EDUCATION	Renovation	10,685	1,143	11,065	26,826	964	-	-	-	-	EDUC_ GENERAL
1	FAU BOCA RATON	55	PHYSICAL SCIENCE	Renovation	4,977	-	26,297	9,079	8,275	-	-	-	1,097	EDUC_ GENERAL
1	FAU BOCA RATON	43	SCIENCE BUILDING	Renovation	988	-	15,162	33,609	17,884	-	-	-	1,252	EDUC_ GENERAL

EPS Survey Year: Amended 2022-2023
University: FAU

Amended Z } u u v New Construction Projects

This report includes the sum of the room areas rolled up at the building level for the five-year Educational Plant Survey report. The buildings are 'New Construction Projects. –

Site ID	Bldg. ID	Building Name	Classroom	Teaching Lab	Study	Research Lab	Office	Gymnasium	Instructional Media	Auditorium	Campus Support Service	Comments
1	0112	Health Sciences Training & Research Facility/Clinical Health Sciences Facility	0	10,000	5,646	35,561	30,580	0	0	0	1,000	Interdisciplinary facility for clinical training in Nursing, Social Work, Psychology; educational and lecture components for small, medium and large groups that take place in flex space.

EPS Survey Year: Amended 2021-2022
University: FAU

Z } u u v Projects for Remodeling

This report includes the sum of the room areas rolled up at the building level for the five-year Educational Plant Survey report. The buildings have been flagged by the University as 'Remodeling. –

Site ID	BldgID	Building Name	Space Type	Classroom	Teaching Lab	Study	

EPS Survey Year: Amended 2022-2023
University: FAU

Z } u u v Renovation Projects

This report includes the sum of the room areas rolled up at the building for the five-year Educational Plant Survey report. The buildings have been flagged by the University as 'Renovation'.

Site ID	Bldg ID	Building Name	Space Type	Classroom	Teaching Lab	Study	Research Lab	Office	Auditorium	Instructional Media	Gym	Campus Support Service	Comments
1	0009	ARTS AND LETTERS	Renovation	6,827	13,406	0	0	8,835	20,334	1,352	0	0	-

AMENDED RECOMMENDATIONS OF THE SURVEY TEAM

2.1* AD Henderson & FAUHS : Media Center will be renovated to the Center for the Advancement of Teacher Development (026C)

2.2* AD Henderson & FAUHS : Classroom 2 will be renovated to the Institute of Biodesign (026D)

2.3 Arts and Letters (0009) : Classroom – 6,827 NASF, Teaching Lab – 13,406 NASF, Office -

Projects Based on Exception Procedure:

The survey team is recommending the following project based on the exception procedure. This project consists of ineligible space; therefore, the Form B space needs formula does not apply.

4.1 No projects were presented.

Demolition:

5.1 No projects were presented.

Site Improvements and Campus -wide Utility Infrastructure: (All Sites)

6.1 Land Acquisition: This is a general recommendation allowing the university to continue purchasing properties surrounding the campus as identified in the adopted Campus Master Plan.

6.2 Landscaping/Site Improvements: This is a general recommendation to continue landscaping, road and site improvements consistent with the adopted Campus Master Plans.

6.3 Utility Infrastructure Improvements: This is a general recommendation to include improvements consisting of items in the categories of chilled water and controls, electrical distributions, storm sewer, sanitary sewer, telecommunications, energy management control systems, irrigation, water distribution, steam equipment and distribution. The projects consist of improvements, extensions, modifications, and additions to the major utility systems consistent with the adopted Campus Master Plan.

Standard University -Wide Recommendations:

SR1: All spaces necessary for custodial and sanitation services in new facilities are recommended.

SR2: All projects for safety corrections are recommended.

SR3: All projects for corrections or modifications necessary to comply with the Americans with Disabilities Act are recommended.

SR4: Any project required to repair or replace a building's components is recommended provided that the total cost of the project does not exceed 25% of the replacement cost of the building.

SR5: Remodeling projects up to $10 million completed pursuant to s. 1011.45(3)(c), F.S. are hereby recommended provided the resulting percentage of Space Needs Met does not exceed 100%.